## 3RF5595

		_	-
DIST.	LTR	51	<u> </u>
0101.		щ	
EDETTI, R.L.	V	ĺ	
11014111	-	Н	-
JAMIN, A.	_	<b>!</b>	_
RMAN, H.S.		ı	
NOU D.D.	-	r	_
ANCH, D.B.	_	١	-
RNIVAL, G.J.		ł	
P, R.D.		1	-
<sup>3</sup> P. H.D.	$\blacksquare$	٠.	
/IS, J.G.		ł	
RERA, D.W.	_	Т	_
THENA, D.VI.	⊢	₽-	-
√NI.B.J.		١	
744441 1 1/	1	۳	
NI, B.J. RMAN, L.K.	_	<b>Ļ</b> .	_
ALY, T.J. DAHL, T.	1	1	
3.41 U. T	1	t	
JAHL, I.	╙	1	
∃IG, J.G.	1	1	
D14 144 4	<del></del>	٠	
BY, W.A.	₽-	1	
ESTER, A.W.	1	1	
- C M	┰	1	_
≟, E.M.	⊢	4	_
NN, H.P.	1	1	
RX, G.E.	1	T	_
AX, G.E.	╄	+	
ONALD, M.M.	1	1	
CANALA E.C.	_	7	
KENNA, F.G.	+-	+	
NTROSE, J.K.	1_	ı.	
RGAN, R.V.	Т	Т	_
TIGATE, TEV.	<b>∔</b>	+	
RGAN, R.V.	L.	L	
ZUTO, V.M.	Т	Т	
57. (11)	+	+	_
EY, J.H.	┸_	1	
VDLIN, N.B.	1	١	
EPLER, R. L.	+-	+	
EPLEN, N. L.	┺	4	
WART, D.L.	1	1	
_LIVAN, M.T.	1	Т	_
LIVAIN, MI.I.	+-	4	_
ANSON, E.R.	ł	1	
KINSON, R.B.	_	т	_
-KINSON, A.B.	╄	4	
LIAMS, S. (ORC	) (	1	
SON, J.M.	Т	Т	
	+-	4	
NE, J.O.	L	j	
	Т	T	
	+-	+	<del></del>
SBY, W.S.	X	1	X
KE, D.Y.Q.	T	T	
(C, D, 1.0).	+	+	
	┸	┙	
iderson, K	T	1	_
MACT THE	+	4	_
	4	_1	
ile'. E.	-13	Л	
/ <del>/ V / V / · · · · · · · · · · · · · · · </del>	-	7	_
	-+-	ᆛ	
rady, T.	- [ 1	V	
	7		
	+	ᅱ	
imrose, A.	دك		
	1		
7	-+-	-	-
TEA	L		
	T		
	+	-	<del></del>
RRES.CONTRO			<u> </u>
MIN RECORD		X	X
	+	÷	<del></del>
AFFIC	ㅗ	!	
	- 1		

## \_ASSIFICATION

ONI		
ICLASSIFIED	X	X
ONFIDENTIAL		
CRET		
		oxdot

JTHORIZED CLASSIFIER SIGNATURE DOUMENT CLASSIFICATION

REVIEW WAIVER PER

ATE CLASSIFICATION OFFIC

REPLY TO RFP CC NO:

OTION ITEM STATUS

ſ	PARTIAL	
'R APP	HOVALE A	١
WSB =	1000	/
RIG,& T	YPIST INITIAL'S	
2 L 4	-C3 - del	

46469 (Boy 3/93)

## 🎝 **EG&G** ROCKY FLATS

EG&G ROCKY FLATS, INC.
ROCKY FLATS PLANT, P.O. BOX 464, GOLDEN, COLORADO 80402-0464 • (303) 966-7000

May 5, 1993

93-RF-5595

Kate Power Woodward Clyde Federal Services Stanford Place 3, Suite 1200 4582 S. Ulster Street Denver, CO 80237

VIOLATION OF HEALTH AND SAFETY PLAN - ALP-022-93

On April 29, the EG&G Corporate Evaluations of Radiological Protection (CERP) team visited the Operable Unit No. 2 (OU 2) drilling operations inside the Americium Zone. Several deficiencies were identified as a result of the evaluation and have been included in the EG&G Corporate Rocky Flats Radiological Evaluation Report. While most of these deficiencies are not the fault or responsibility of Woodward Clyde, some are.

Specifically, the drill site and step off pad were not in compliance with the radiological posting requirements and were in violation of the OU2 Health and Safety Plan. In the future, all postings will be in accordance with approved procedures. Woodward-Clyde is directed to strictly comply with this request. A second Health and Safety violation will result in loss of the contract.

It is my understanding that the step-off pad was not posted due to a miscommunication in response to an Occupational Safety and Health Administration (OSHA) finding. Therefore, directions to change health and safety practices will not be followed unless these are in writing and approved by Keith Anderson, Environmental Restoration Management Health and Safety, or his designee. This will not include directions issued due to immediate dangers to safety or health.

anutt L. Primore

Annette L. Primrose Project Manager for OU 2

ERM/Remediation Project Management

dal

UNU

direct sometime description of the company of the c	the state of the s	•
REVIEWED	TOR CLASSIFICATION/LICH	
RY	G. T. Ostdiek	
DATE	6-4-93	
18/11 in manner	Continues to the Continues of the Contin	